

BULLETIN

July 7, 1998

To: ALL SUBURBAN WATER HEATER OWNERS

The purpose of this bulletin is to alert you to a potential safety hazard that may exist whenever inexperienced personnel perform repairs to your water heater. We have learned that it is possible for the main burner orifice to fall out of the burner when the manifold tubing is removed from the burner. If unnoticed, and the orifice is not in place when the tubing is reinstalled, gas flow will be excessive. This could result in flame damage to your RV or even personal injury. Therefore, it is imperative, following any repairs requiring removal of the manifold tube from the burner, and before reconnecting the manifold tube to the burner, that a visual check be made of the burner by the person performing the repairs to assure that the orifice is in place.

This bulletin is only applicable to Suburban water heaters within the following serial number range: 953401118 to 974400950.

Enclosed is a label repeating this precautionary notice. Please apply this label to the water heater compartment housing where it will be visible when the door is opened.

